Account #: # of Units:	218.11-1-8
Unit Address:	414 Oquaga Lake
Billing Name:	K&P Real Properties LLC
Billing Address:	180 East Front St
	Hancock, NY 13783

		Date	Date	Date Tank	Date Pump		
_	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
_	5/9/2023		4/19/2023			Add to pump list	



Account #: # of Units: Unit Address:	218.11-1-9 418 Oquaga Lake
Billing Name: Billing Address:	David Paparoski 42 Kent Rd Hillsdale, NJ 07642

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.11-1-12
Unit Address:	426 Oquaga Lake
Billing Name:	David Nolan
Billing Address:	PO Box 35
	Deposit, NY 13754-0035

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units: Unit Address:	218.11-1-14 5 Hanson
Billing Name: Billing Address:	David R Schroeder PO Box 136 Tenafly, NJ 07670
Tank #1	

	Date	Date	Date Tank	Date Pump
Report Date	Pumped	Inspected	Replaced	Replaced
9/12/2023				

Account Notes: 8/2/23: met w/Dave went over locations of tanks on 2 properties and plans to relocate next year



Account #: # of Units:	218.11-1-15
Unit Address:	15 Hanson
Billing Name: Billing Address:	Harry S Fenson Trust 623 Ventura Blvd #1 S Endwell, NY 13760

		Date	Date	Date Tank	Date Pump		
	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
_	5/9/2023		4/24/2023		No Pump	Gravity tank - looked good	





Account #: # of Units:	218.11-1-19
Unit Address:	12 Hanson
Billing Name: Billing Address:	Ronald Menichetti 6270 Arbor Valley Ave Las Vegas, NV 89139

Report Date	Date Pumped	Date Inspected	Date Pump Replaced
6/13/2023		5/8/2023	
5/9/2023		4/19/2023	

Winter Address:		Summer Address:
	6270 Arbor Valley Ave	12 Hanson Rd
	Las Vegas, NV 89139	Deposit, NY 13754

Account Notes:

Replaced alarm float, needs new light bulb Alarm float needs to be replaced, Solids tank thick - add to pump list, pulled stuck concrete cover out.



218.11-1-21
22 Hanson
David F Smith
883 River Rd
Deposit, NY 13754

Report Date	Date Pumped	Date Inspected	Date Tank Replaced	Date Pump Replaced	Account Notes:
5/9/2023	-	4/17/2023	-		Solids Tank Thick - Pump ASAP, needs plywood cover, needs new alarm float
6/13/2023		5/1/2023			Put new plywood in solids tank



Account #: # of Units:	218.11-1-22
Unit Address:	26 Hanson
Billing Name:	K B Joscelyn LLC
Billing Address:	11 Southwick Ct
	Ann Arbor, MI 48105

	Report Date	Date Pumped	Date Inspected	Date Tank Replaced	Date Pump Replaced	Account Notes:
_	6/13/2023		5/8/2023	Power on, looks good and working		
	5/9/2023		4/17/2023		5/28/2018	Tanks Full: Add to "Pump ASAP" list, no power showing in box will double check



Account #: # of Units:	218.11-1-23
Unit Address:	32 Hanson
Billing Name:	Toni O'Hanlon
Billing Address:	547 Manor Bridge Rd
	Pelham Manor, NY 10803

Report Date	Date Pumped	Date Inspected	Date Tank Replaced	Date Pump Replaced	Account Notes:
6/13/2023		5/8/2023			secured pump float
5/9/2023		4/17/2023			new floats and pump working, maybe leaking



Account #:	218.11-1-24
# of Units: Unit Address:	36 Hanson
Billing Name:	Miriam Caroline Truesdell
Billing Address:	c/o Walter Truesdell
	306 E 90th St
	New York, NY 10128
Tank #1	

		Date	Date	Date Tank	Date Pump		
_	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
_	5/9/2023		4/19/2023			Good Shape	



Account #: # of Units:	218.11-1-25
Unit Address:	38 Hanson
Billing Name:	Mary M Mathis
Billing Address:	43 Helen St
	Binghamton, NY 13905

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.11-1-26
Unit Address:	42 Hanson
Billing Name:	Marie A Davenport
Billing Address:	84 Grand Blvd Binghamton, NY 13905
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.11-1-27
# of Units:	
Unit Address:	44 Hanson
Billing Name:	Jennifer Locke
Billing Address:	1 Cornell Dr
	Randolph, NJ 07869

	Date	Date	Date Tank	Date Pump		
 Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
 5/9/2023		4/17/2023		5/30/2012	Add to pump list: solid tank not too bad	



Account #:	218.11-1-28
# of Units:	
Unit Address:	46 Hanson
Billing Name:	Thomas Mott
Billing Address:	619 Lowell Dr
	Endwell, NY 13760

		Date	Date	Date Tank	Date Pump		
_	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
	5/9/2023		4/17/2023			Solids Tank thick - going on pump list ASAP	_



Account #: # of Units:	218.11-1-29.1
Unit Address:	425 Oquaga Lake
Billing Name:	Barbara J Sarkisian
Billing Address:	PO Box 1925
	Binghamton, NY 13902

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.11-1-30
Unit Address:	421 Oquaga Lake
Billing Name:	Mark B Yonaty
Billing Address:	45 Lewis St
	Binghamton, NY 13901

	Report Date	Date Pumped	Date Inspected	Date Pump Replaced
-	2/14/2023		1/12/2023	
	6/13/2023		5/8/2023	

SUMMA

Account Notes: Tank being replaced, scheduled ASAP. Quote coming soon to get leaking tank replaced Both Tanks need replacement; both have lots of water running in (took pics). Replacing ASAP



Account #: # of Units:	218.11-1-32
Unit Address:	417 Oquaga Lake
Billing Name:	June B Nolan
Billing Address:	PO Box 35
-	Deposit, NY 13754
Tank #1	

I ank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Report Date

Account #:	218.11-1-33								
# of Units:									
Unit Address:	4	413 Oquaga Lake							
Billing Name:	David M Race								
Billing Address:	& Kera	Martin-Race	Rev Trust						
0	702 (Crystal Mour	ntain Dr						
Austin, TX 78733									
Tank #1									
	Date	Date	Date Tank	Date Pump					

Replaced

Replaced Account Notes:

Pumped Inspected

SUMMARY

Account #: # of Units:	218.11-1-34
Unit Address:	407 Oquaga Lake
Billing Name:	Rowe Family Rev Trust
Billing Address:	407 Oquaga Lake Rd
	Deposit, NY 13754

		Date	Date	Date Tank	Date Pump		
_	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
	5/9/2023		4/19/2023			Needs new alarm float, solids tank thick: add to pump list for this year	_



Account #:	218.12-1-3			
# of Units:				
Unit Address:	95 Hanson			
Billing Name:	Seymour J Klionsky			
Billing Address:	3499 Byron Ln			
	Longboat Key, FL 34228			

Tank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: 218.12-1-5 # of Units:			
Unit Address:	85 Hanson		
Billing Name: Billing Address:	Charles E Kramer 37 Mill St		
	Binghamton, NY 13903		

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-7
Unit Address:	81 Hanson
Billing Name:	Richard Gaska
Billing Address:	24 N Morningside Dr
	Binghamton, NY 13905

Report Date	Date Pumped	Date Inspected	Date Tank Replaced	Date Pump Replaced	Account Notes:
6/13/2023		5/9/2023			Pump tank leaking right out of bottom of tank needs to be replaced ASAP
5/9/2023	7/28/2019	4/24/2023		7/28/2019	Need new floats asap, both floats stuck and had water in them



Account #: # of Units:	218.12-1-12
Unit Address:	67 Hanson
Billing Name:	Patrick Quinn
Billing Address:	11 Giles St

Binghamton, NY 13905

Tank #1

	Date	Date	Date Tank	Date Pump	
 Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:
 5/9/2023		4/24/2023			Good shape



Account #: # of Units:	218.12-1-13				
Unit Address:	61 Hanson				
Billing Name: Billing Address:	Linda A Hamilton 53 Matthew Dr Binghamton, NY 13901				

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-15
Unit Address:	51 Hanson
Billing Name:	Koenraad A Gieskes
Billing Address:	48 Hanson Rd
	Deposit, NY 13754

	Date	Date	Date Tank	Date Pump		
 Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
 5/9/2023	7/22/2020	4/24/2023		7/22/2020	in good shape	



Account #: # of Units:	218.12-1-20.1
Unit Address:	790 Oquaga Lake
Billing Name:	Anna-Kate Schneider
Billing Address:	47 Lounsbury Pl Kingston, NY 12401
Taulu #4	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-21
# of Units:	
Unit Address:	48 Hanson
Billing Name:	Koenraad Gieskes
Billing Address:	48 Hanson Rd
	Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Report Date	Date Pumped	Date Inspected	Date Tank Replaced	Date Pump Replaced	Account Notes:	
Tank #1						
	Wil	mington, DE 1	9803			
	Surrey Park					
Billing Address:		214 Paddock L	_n			
Billing Name:	Joseph J Mesa					
Unit Address:		52 Hanson				
Account #: # of Units:	218.12-1-22					



Account #: # of Units:	218.12-1-23
Unit Address:	54 Hanson
Billing Name:	Joseph F Rogers
Billing Address:	54 Hanson Rd
	Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Report Date

Account #: # of Units:	218.12-1-24					
Unit Address:		56 Hanson			Winter Address:	Summer Address:
Billing Name:	R	ichard D La	ng			
Billing Address:	-	776 Pier Lar	e		776 Pier Lane	60 Highland Rd
	Melbou	rne Beach, I	EL 32951		Melbourne Beach, FL 32951	Binghamton, NY 13901
Tank #1						
	Date	Date	Date Tank	Date Pump		

Account Notes:

Replaced

Pumped Inspected Replaced



Account #: # of Units:	218.12-1-25
Unit Address:	58 Hanson
Billing Name: Billing Address:	Margaret R. Ruhnke Rev Trust 17 Old Field Pl Rowayton, CT 06853

Tank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units: Unit Address:	218.12-1-26 62 Hanson
Billing Name: Billing Address:	Leonard G Pasquale PO Box 257 Binghamton, NY 13903
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-27
Unit Address:	64 Hanson
Billing Name:	Edwin C Wilmarth Trust
Billing Address:	64 Hanson Rd
	Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-28
Unit Address:	66 Hanson
Billing Name:	WE Leasing NY LLC
Billing Address:	PO Box 491 Chenango Bridge, NY 13745
T 1- #4	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-29
# of Units:	
Unit Address:	68 Hanson
Billing Name:	Benjamin Hanson
Billing Address:	51 Woodland Dr
-	Big Flats, NY 14814

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-30
Unit Address:	70 Hanson
Billing Name: Billing Address:	Monica Tremonti Rev Trust 2002 August Dr Silver Spring, MD 20902
	Silver Spring, MD 20902

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-31	
# of Units: Unit Address:	72 Hanson	
Billing Name: Billing Address:	Rek Corp 300 Plaza Drive Box 1568 Vestal, NY 13850	
Tank #1		

Tan	k i	#1
-----	-----	----

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units: Unit Address:	218.12-1-32 76 Hanson
Billing Name: Billing Address:	Tina R Feinberg 503 Plaza Dr Ste 100 Vestal, NY 13850
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-33
Unit Address:	80 Hanson
Billing Name: Billing Address:	Michael J Fidler 4850 Osprey Dr Apt 205 St. Petersburg, FL 33711

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-34
# of Units:	22 1 1
Unit Address:	82 Hanson
Billing Name:	James R Peduto
Billing Address:	1505 Buffalo St
	Endicott, NY 13760
Tank #1	

I ank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-37.1	
# of Units: Unit Address:	88 Hanson	
Billing Name:	Richard J Duggan	
Billing Address:	300 Canyon Oaks Dr	
	Wimberley, TX 78676	
Tank #1		

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-38
Unit Address:	92 Hanson
Billing Name: Billing Address:	Timothy J Koval 9141 E Cottonwood Ct Tucson, AZ 85749
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-39
Unit Address:	96 Hanson
Billing Name: Billing Address:	Seymour J Klionsky Trust 3499 Byron Ln Longboat Key, FL 34228
Topk #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Report Date	Date Pumped	Date Inspected	Date Tank Replaced	Date Pump Replaced	Account Notes:
Tank #1					
	D	eposit, NY 137	754		
		7 Lippincott P	2		
Billing Address:		c/o Alice Marti	in		
Billing Name:	Ν	lary Ann Wald	ron		
Unit Address:		100 Hanson			
Account #: # of Units:	218.12-1-40)			



Account #: # of Units:	218.12-1-41
Unit Address:	102 Hanson
Billing Name: Billing Address:	McDonough Qlfd Per Res Trust 236 Cheshire Way Naples, FL 34110
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-43.1		
Unit Address:	106 Hanson	Winter Address:	Summer Address:
Billing Name: Billing Address:	Elaine K Reinhardt 2930 Ashley Dr, E. Villa C	2930 Ashley Dr, E. Villa C	106 Hanson Rd
Ū	West Palm Beach, FL 33415	West Palm Beach, FL 33415	Deposit, NY 13754
Tank #1	Dete Dete Dete Terris Det		

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-45
# of Units: Unit Address:	811 Oquaga Lake
Billing Name:	Ladd G Dawson
Billing Address:	811 Oquaga Lake Rd
	Deposit, NY 13754
Tank #1	

I ank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-47
Unit Address:	789.1 Oquaga Lake
Billing Name:	David Paparoski
Billing Address:	42 Kent Rd
	Hillsdale, NJ 07642

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-48
Unit Address:	77 Oquaga Lake
Billing Name:	David Paparoski
Billing Address:	42 Kent Rd Hillsdale, NJ 07642

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-49
Unit Address:	799 Oquaga Lake
Billing Name: Billing Address:	Barbara L Marko 799 Oquaga Lake Rd Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-50				
# of Units:					
Unit Address:	795 Oquaga Lake				
Billing Name:	Leo W Race				
Billing Address:	8957 N Fitzgerald Ln				
	Tucson, AZ 85742				
T H 4					

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-52
Unit Address:	787 Oquaga Lake
Billing Name:	Michael Mulcahy
Billing Address:	1400 Raritan Rd
	Scotch Plains, NJ 07076

	Date	Date	Date Tank	Date Pump		
 Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
 8/8/2023					Put on pump list	



Account #:	218.12-1-53
# of Units: Unit Address:	781 Oquaga Lake
Billing Name:	Matthew S Tenser
Billing Address:	781 Oquaga Lake Rd
	Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units: Unit Address:	218.12-1-55			
	789.2 Oquaga Lake			
Billing Name: Billing Address:	Sarah J Behnke 105 Gates St			
billing Address.	Binghamton, NY 13903			

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-56			
Unit Address:	789.3 Oquaga Lake Rear			
Billing Name: Billing Address:	Alllison L Weissman 16 Robin Ct Poughquag, NY 12570			

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-57			
# of Units: Unit Address:	791 Oquaga Lake			
Billing Name:	Sharon R Simkin Trust			
Billing Address:	4902 N Rock Spring Rd Arlington, VA 22207			
Tank #1				

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.12-1-59.1
# of Units: Unit Address:	791 1/8 Oquaga Lake
Billing Name:	Timothy B Brandi
Billing Address:	3 Oldham Pl
-	Wilton, NY 12831

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-60.1				
Unit Address:	110 Hanson				
Billing Name:	Ladd G Dawson				
Billing Address:	811 Oquaga Lake Rd Deposit, NY 13754				

	Date	Date	Date Tank	Date Pump		
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
9/12/2023	8/8/2023	8/8/2023		8/8/2023	1HP pump was 11 yrs old; tanks pumped, checked, pump replaced	
					Red light, tank levels up, pump not working, tanks pumped out, pump	
10/10/2023	9/25/2023	9/25/2023			plugged: fixed, hookedup and tested, in good shape	



Account #: # of Units:	218.12-1-61
Unit Address:	104 Hanson
Billing Name:	Paul R Hoffmann
Billing Address:	2652 Clearview Dr
	Endwell, NY 13760
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.12-1-62
# of Onits. Unit Address:	786 Oquaga Lake
Billing Name:	Jesse Stevens
Billing Address:	786 Oquaga Lake Rd
	Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-3
Unit Address:	452 Oquaga Lake
Billing Name:	Donald J Buck
Billing Address:	27 Locust Ave
	Redbank, NJ 07701

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-8
Unit Address:	121 Oquaga Laka
Unit Address.	431 Oquaga Lake
Billing Name:	Barbara J Sarkisian 3 Year Trust
Billing Address:	11 Charlotte St
	Binghamton, NY 13905

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-9
Unit Address:	437 Oquaga Lake
Billing Name:	Mark P Millspaugh
Billing Address:	800 Avon Crest Blvd
	Schenectady, NY 12309

	Date	Date	Date Tank	Date Pump		
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
6/13/2023		5/8/2023			Replaced Alarm Float	
6/13/2023		5/11/2023			Replaced Pump with 1/2 hp pump	



Account #: # of Units:	218.15-1-10
Unit Address:	435 Oquaga Lake
Billing Name:	Oquaga Firewood LLC
Billing Address:	10 Jessup St
	Walden, NY 12586
T 1- #4	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-11
Unit Address:	439 Oquaga Lake
Billing Name: Billing Address:	Wildwood Holding LLC 800 Avon Crest Blvd
	Schenectady, NY 12309

	Date	Date	Date Tank	Date Pump	
 Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:
 6/13/2023		5/8/2023			Looks good, added to pump list for later on.



Account #:	218.15-1-12.1
# of Units: Unit Address:	443 Oquaga Lake
Billing Name:	Seth Farbman
Billing Address:	449 Oquaga Lake Rd
	Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.15-1-13
# of Units: Unit Address:	449 Oquaga Lake
Billing Name:	Carola Delmarle
Billing Address:	449 Oquaga Lake Rd
	Deposit, NY 13754
Tank #1	

I ank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.15-1-14	l i					
# of Units: Unit Address:	4	I51 Oquaga La	lke				
Billing Name:	Axtell	Family Compa	any LLC				
Billing Address:		Margaret Axte					
-	733 Dividing Rd						
	Severna Park, MD 21146						
Tank #1							
	Date	Date	Date Tank	Date Pump			
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:		



Account #:	218.15-1-15
# of Units:	
Unit Address:	459 Oquaga Lake
Billing Name:	Jason Kerwar
Billing Address:	101 Croton Ave
	Mt Kisco, NY 10549

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.15-1-16
# of Units:	
Unit Address:	461 Oquaga Lake
Billing Name:	John Deuel
Billing Address:	43829 N Ericson Ln
-	New River, AZ 80587

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-17	
Unit Address:	465 Oquaga Lake	
Billing Name: Billing Address:	Hisham Kashou 20 Clifton Blvd Binghamton, NY 13903	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-18
Unit Address:	469 Oquaga Lake
Billing Name: Billing Address:	Lindsay Phelps 1324 N Greenview Ave #1 Chicago, IL 60642

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-19
Unit Address:	471 Oquaga Lake
Billing Name: Billing Address:	Daniel L Sambursky 28 Mountain Brook Dr Vestal, NY 13850

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-21
Unit Address:	475 Oquaga Lake
Billing Name:	Albert Nocciolino
Billing Address:	18 Riverside Dr
0	Binghamton, NY 13905

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.15-1-22
# of Units: Unit Address:	479 Oguaga Lake
Billing Name:	Paulsen Properties LLC
Billing Address:	2112 Kypriotis Dr
	Cortland, NY 13045
Topk #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-23	3			
Unit Address:	2	187 Oquaga La			
Billing Name:	Jame	es Shreve Irrev	. Trust		
Billing Address:		c/o Kate Shrev	/e		
	8401	Brownes Pon			
	C	harlotte, NC 28	3277		
Tank #1					
Report Date	Date Pumped	Date Inspected	Date Tank Replaced	Date Pump Replaced	Account Notes:



Account #:	218.15-1-24
# of Units:	
Unit Address:	491 Oquaga Lake
Billing Name:	David S. Molter
Billing Address:	4001 Saddlemire Rd
-	Binghamton, NY 13903

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.15-1-25.2
# of Units: Unit Address:	493 Oquaga Lake
Dilling Name:	Cine Mellush
Billing Name: Billing Address:	Gina McHugh 27 Clifton Blvd
Dilling Address.	Binghamton, NY 13903
	Dinghamon, NT 15905
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.15-1-26
Unit Address:	495 Oquaga Lake
Billing Name:	Gina McHugh
Billing Address:	27 Clifton Blvd
	Binghamton, NY 13903

		Date	Date	Date Tank	Date Pump	
_	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:
_	5/13/2023		5/6/2023			Putting on Pump List





Account #: 218.15-1-29.1 # of Units: Unit Address: 505 Oquaga Lake Billing Name: W&D Leasing LLC Billing Address: PO Box 491 Chenango Bridge, NY 13745

Report Date	Date Pumped	Date Inspected		Date Pump Replaced
6/13/2023		5/1/2023		
6/13/2023	5/31/2023	5/31/2023	5/31/2023	

Account Notes:

Breaker inside tripped, tank full of water, been offline for 10+ years, will be assessing situation ASAP: May be replacing Grease Tank leaking in bottom: Replaced Grease Tank



Account #: # of Units:	218.16-1-1.1		
# of Onits: Unit Address:	773 Oquaga Lake	Winter Address:	Summer Address:
Billing Name:	William J. Hanratty		
Billing Address:	773 Oquaga Lake Rd Deposit, NY 13754	50 Brookside Ln Little Silver, NJ 07739	773 Oquaga Lake Rd Deposit, NY 13754
Tank #1			<u> </u>

Date Date Date Tank Date Pump Report Date Pumped Inspected Replaced Replaced

Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:		
					Changed alarm float	, putting on list to pump so we can check	
6/13/2023		5/16/2023			solids tank soon		





Account #: # of Units:	218.16-1-1.2			
Unit Address:	771 Oquaga Lake			
Billing Name: Billing Address:	Cynthia A. Rotella 771 Oguaga Lake Rd			
5	Deposit, NY 13754			

	Date	Date	Date Tank	Date Pump		
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
6/13/2023		5/15/2023			Add to Pump list, Floats need to be replaced ASAP	
					Changed pump, pump tripped breaker, level was odd - must be	
					leaking. Got Mike Williams: told him we need to add another pump	
6/13/2023		5/16/2023			tank	



Account #: # of Units:	218.16-1-3			
Unit Address:	767 Oquaga Lake			
Billing Name:	Ross E. Depietro			
Billing Address:	22 Eagle Dr			
	N. Kingstown, RI 02852-1056			

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-4
Unit Address:	765 Oquaga Lake
Billing Name:	Brad C. Phillips
Billing Address:	60 Matthews Dr
	Binghamton, NY 13901

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-5
# of Units: Unit Address:	763 Oquaga Lake
Unit Address.	703 Oquaya Lake
Billing Name:	Joseph R. Weiss
Billing Address:	1544 E 28th St
	Brooklyn, NY 11229
T	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-6
# of Units:	
Unit Address:	761 Oquaga Lake
Billing Name:	Robert Schneider
Billing Address:	12 Fairway Dr
	Asheville, NC 28805

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-9
Unit Address:	755 Oquaga Lake
Billing Name:	Joan M. Crowley
Billing Address:	66 Kenilworth Rd
Billing / laar ooo.	
	Binghamton, NY 13903

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-10.2
# of Units: Unit Address:	753 Oquaga Lake
Billing Name: Billing Address:	Lila Marie Kashou McKenna 708 Murray Hill Rd
0	Vestal, NY 13850
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-11
Unit Address:	751 Oquaga Lake
Billing Name:	Charles Lesko, Jr.
•	
Billing Address:	703 Front St
	Binghamton, NY 13905

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-12
Unit Address:	749 Oquaga Lake
Billing Name:	David L. Cramer
Billing Address:	749 Oquaga Lake Rd
	Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-13
Unit Address:	745 Oquaga Lake
Billing Name: Billing Address:	Mara Y. Grace 3712 Maplehurst Dr
Dilling Address.	Endwell, NY 13760
Tank #1	

I ank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-14
Unit Address:	743 Oquaga Lake
Billing Name:	Jay C. Larrabee
Billing Address:	4846 State Route 80
-	Tully, NY 13159

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-15
# of Units: Unit Address:	739 Oquaga Lake
Billing Name:	David Bruce MacInnes
Billing Address:	2114 Oak Branch Blvd
	Sebring, FL 33875
Taul #4	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-16
# of Units: Unit Address:	737 Oquaga Lake
Billing Name: Billing Address:	Thierry Horner 620 Baron Dekalb Rd Wayne, PA 19087
Tank #1	

I ank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-17
Unit Address:	735 Oquaga Lake
Billing Name:	Andrew Francis Sears, Jr
Billing Address:	484 Broadway Dobbs Ferry, NY 10522

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-18
Unit Address:	733 Oquaga Lake
Billing Name:	Richard A. Stram
Billing Address:	508 Murray Hill Rd
	Vestal, NY 13850
Tool #4	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-19
Unit Address:	731 Oquaga Lake
Billing Name: Billing Address:	Farrell Irrev. Trust, Janice 731 Oquaga Lake Rd Deposit, NY 13754

	Date	Date	Date Tank	Date Pump		
 Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
 6/13/2023		5/15/2023			Add to Pump list ASAP	





Account #:	218.16-1-20
# of Units:	
Unit Address:	727 Oquaga Lake
Billing Name:	Cathy Depew
Billing Address:	727 Oquaga Lake Rd
	Deposit, NY 13754

		Date	Date	Date Tank	Date Pump		
_	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
_	6/13/2023		5/15/2023			Put on Pump list ASAP	





Account #:	218.16-1-21	
# of Units: Unit Address:	725 Oquaqa Lake	
Unit Address.	725 Oquaga Lake	
Billing Name:	Lenore Lupie	
Billing Address:	78 Roundabend Rd	
	Tarrytown, NY 10591	
T		

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-22
Unit Address:	723 Oquaga Lake
Billing Name:	Jennifer L. Costa
Billing Address:	1803 Snyder Ave
-	Belmar, NJ 07719

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-23
Unit Address:	719 Oquaga Lake
Billing Name:	Hans T. Gieskes
Billing Address:	26 Abbey Rd
	Westwood, MA 02090-2961

		Date	Date	Date Tank	Date Pump		
_	Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
	2/14/2023		1/10/2023			Checked, tested floats, pump - pump tank, normal level	



Account #:	218.16-1-24
# of Units: Unit Address:	713 Oquaga Lake
Billing Name:	Schneider Dec. of Trust
Billing Address:	4949 S. 60th St
	St. Petersburg, FL 33715

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-25
Unit Address:	711 Oquaga Lake
Billing Name:	Kurt Acker
Billing Address:	711 Oquaga Lake Rd
	Deposit, NY 13754

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-26				
Unit Address:	707 Oquaga Lake				
Billing Name: Billing Address:	Kurt Acker 711 Oquaga Lake Rd				
	Deposit, NY 13754				
Tauls 44					

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-27
# of Units:	
Unit Address:	703 Oquaga Lake
Billing Name:	George Slavik
Billing Address:	9 Carolyn Ct
-	Endwell, NY 13760

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-28
# of Units: Unit Address:	699 Oquaga Lake
Billing Name: Billing Address:	Anthony R. Paniccia 300 N. Hudson St Johnson City, NY 13790

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-29
# of Units:	
Unit Address:	695 Oquaga Lake
Billing Name:	Frances Libous
Billing Address:	5 Riverside Dr. Apt 1101
	Binghamton, NY 13901

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.16-1-30				
Unit Address:	683 Oquaga Lake				
Billing Name:	Jacqueline Michelle Debs				
Billing Address:	436 72nd St				
	Brooklyn, NY 11209				
T 1 #4					

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-33
# of Units: Unit Address:	770 Oquaga Lake
Billing Name: Billing Address:	Alexander L. Chalmers 770 Oquaga Lake Rd Deposit, NY 13754
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-37
# of Units:	
Unit Address:	698 Oquaga Lake
Billing Name:	Thomas Libous (Estate)
Billing Address:	5 Riverside Dr Apt 1101
-	Binghamton, NY 13905

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.16-1-38
# of Units: Unit Address:	704 Oquaga Lake
Billing Name: Billing Address:	Oquaga Lake Life LLC 9 Carolyn Ct Endwell, NY 13760
Tank #1	

I ank #1

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.19-1-9
Unit Address:	517 Oquaga Lake
Billing Name: Billing Address:	William R. Maines PO Box 491 Chenango Bridge, NY 13745

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.19-1-11
# of Units: Unit Address:	519 Oquaga Lake
Billing Name:	Curt F. Fenkl
Billing Address:	25 Deborah Dr
	Johnson City, NY 13790

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.19-1-12
Unit Address:	521 Oquaga Lake
Billing Name: Billing Address:	William R. Maines PO Box 491 Chenango Bridge, NY 13745

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.19-1-14
# of Units: Unit Address:	525 Oquaga Lake
Billing Name: Billing Address:	Curt F. Fenkl 25 Deborah Dr Johnson City, NY 13790

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.19-1-15
# of Units: Unit Address:	531 Oquaga Lake
Billing Name: Billing Address:	Binghamton Giant Markets Inc. PO Box 895 Vestal, NY 13851

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.19-1-16
Unit Address:	537 Oquaga Lake
Billing Name:	Bridget O'Connor
Billing Address:	10 Beacon Street
	Binghamton, NY 13901

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:
8/8/2023		7/17/2023		2 years ago	Pump float was stuck, alarm float bad, water in tank scheduled to replace ASAP
8/8/2023		7/25/2023			10,000 Gal Tank: Changed alarm float, pumped out big tank



Account #: # of Units:	218.19-1-18
Unit Address:	543 Oquaga Lake
Billing Name:	Louise Akel
Billing Address:	221 Riverside Dr
-	Binghamton, NY 13905

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	218.20-1-1
# of Units:	
Unit Address:	551 Oquaga Lake
Billing Name:	Marquis Deposit LLC
Billing Address:	644 South Figueroa St
	Los Angeles, CA 90017

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.20-1-3
Unit Address:	633 Oquaga Lake
Billing Name:	Marquis Deposit LLC
Billing Address:	644 South Figueroa St
-	Los Angeles, CA 90017

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #: # of Units:	218.20-1-4
Unit Address:	675 Oquaga Lake
Billing Name:	Gary Holdrege
Billing Address:	675 Oquaga Lake Rd
	Deposit, NY 13754

	Date	Date	Date Tank	Date Pump		
 Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:	
 4/11/2023	3/28/2023	3/29/2023			Replaced alarm float, pump functioning, leak in solids tank	



Account #: # of Units:	218.20-1-6
Unit Address:	672 Oquaga Lake
Billing Name:	Edward M. Eisele
Billing Address:	241-42 86th Ave
Billing / laar ooo.	
	Bellerose, NY 11426

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Town of Sanfo Sewer O & M 91 Second St Deposit, NY 137					
Account #:	218.20-1-7				
# of Units: Unit Address:	6	67 Oquaga La	ike		
Billing Name:	Scott	's Oquaga Rea	lty LLC		
Billing Address:	c/o C	harles Allen, M	lanager		
	1	4259 Ashland	Rd		
	Gle	en Allen, VA 23	3059		
Tank #1					
	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:



Account #:	235.02-1-4.1
# of Units: Unit Address:	567 Oquaga Lake
Billing Name:	Marquis Deposit LLC
Billing Address:	644 South Figueroa St
	Los Angeles, CA 90017
Tank #1	

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:





Account #: # of Units:	235.02-1-13.12
Unit Address:	668 Oquaga Lake
Billing Name:	Marquis Deposit LLC
Billing Address:	644 South Figueroa St
	Los Angeles, CA 90017

	Date	Date	Date Tank	Date Pump	
Report Date	Pumped	Inspected	Replaced	Replaced	Account Notes:

